

25X1A

ORIG: [REDACTED]
 UNIT:
 EXT:
 DATE: 12 OCT 71
 ROUTING

FILE NUMBER

Approved For Release 2002/10/16 : CIA-RDP74B00496R000400010027-5

C-311-C

Comments regarding reference(s)

205

1	D/M	8	RB	11		16		21
2	D/M	7	D/O	12		17		22
3	D/M	8	INTEL	13		18		23
4	D/M	9	SAS	14		19		24
5	D/SA	10	INTEL	15		20		25

(classification)

SECRET

(date and time filed)

12 16 00 02 OCT 71

(elite)

(reference number)

(elite)

(reference number)

CITE

6133

25X1A

25X1A

TO [REDACTED]

PRIORITY [REDACTED]

25X1

REF: [REDACTED]

25X1A

SUBJ: HSN C-311-C LONG SHAFT

1. PLS ANSWER FOLLOWING QUESTIONS:

- A. WAS ANTIFUNGUS COATING WHICH CAUSED PROBLEMS APPLIED AT VENDOR PLANT OR IN FIELD?
- B. DID PRE-FLIGHT INDICATE SYSTEM OPERATING CORRECTLY?
- C. ANY THOUGHTS AS TO WHY THIS DEFICIENCY DID NOT SHOW UP DURING LOCK-OUT MOD TEST FLIGHTS.

END OF MESSAGE

3 2 3 2 1

25X1A

AUTHENTICATING OFFICER

COORDINATING OFFICERS

SECRET

GROUP I
 Subject does not contain
 recommendations and
 conclusions

D/M/OSA
 RELEASING OFFICER

Approved For Release 2002/10/16 : CIA-RDP74B00496R000400010027-5

Copy No.